

February 6, 2023 Inspections

Inspections for Andy McCune

	Permit #	Address	AM/PM	Inspection Type
1	B23-00026	1804 MORNING DOVE LN	AM	Building - Final
2	B23-00026	1804 MORNING DOVE LN	AM	Electric Conduit
3	B23-00026	1804 MORNING DOVE LN	AM	Electric Wire
4	B22-02346	627 CENTER CREST DR	AM	Electric Conduit
5	B22-02346	627 CENTER CREST DR	AM	Building - Final
6	B22-02346	627 CENTER CREST DR	AM	Electric Wire
7	B22-02346	627 CENTER CREST DR	AM	Electric Service
8	B23-00056	345 FRANKLIN AVE	AM	Roof Deck
9	B22-01068	1018 CAMPUS AVE	AM	Pool Fence/Gate
10	B22-01068	1018 CAMPUS AVE	AM	Pool Equipotential
11	B22-02719	1536 CLAY ST	AM	Building - Final
12	B22-02477	908 HALF MOON AVE	PM	Forms and Footings
13	B22-02477	908 HALF MOON AVE	PM	Slab on Grade
14	B22-02476	916 HALF MOON AVE	PM	Forms and Footings
15	B22-02476	916 HALF MOON AVE	PM	Slab on Grade
16	B22-02475	922 HALF MOON AVE	PM	Forms and Footings
17	B22-02475	922 HALF MOON AVE	PM	Slab on Grade
18	B22-02474	928 HALF MOON AVE	PM	Forms and Footings
19	B22-02474	928 HALF MOON AVE	PM	Slab on Grade
20	B22-01881	1767 MARDI GRAS LN	AM	Insulation
21	B22-01882	1766 MARDI GRAS LN	PM	Insulation
22	B22-02487	845 ORANGEDALE AVE	PM	Sewer Lateral
23	B22-02487	845 ORANGEDALE AVE	PM	Ground Plumbing
24	B22-02487	845 ORANGEDALE AVE	PM	Water Pipe - Underground
25	B22-02486	835 ORANGEDALE AVE	PM	Sewer Lateral
26	B22-02486	835 ORANGEDALE AVE	PM	Ground Plumbing
27	B22-02486	835 ORANGEDALE AVE	PM	Water Pipe - Underground
28	B22-02485	828 ORANGEDALE AVE	PM	Sewer Lateral
29	B22-02485	828 ORANGEDALE AVE	PM	Ground Plumbing
30	B22-02485	828 ORANGEDALE AVE	PM	Underground Conduit
31	B22-02485	828 ORANGEDALE AVE	PM	Water Pipe - Underground
32	B22-02484	834 ORANGEDALE AVE	PM	Sewer Lateral
33	B22-02484	834 ORANGEDALE AVE	AM	Ground Plumbing
34	B22-02484	834 ORANGEDALE AVE	PM	Underground Conduit
35	B22-02484	834 ORANGEDALE AVE	PM	Water Pipe - Underground
36	B22-02483	840 ORANGEDALE AVE	PM	Sewer Lateral
37	B22-02483	840 ORANGEDALE AVE	PM	Ground Plumbing
38	B22-02483	840 ORANGEDALE AVE	PM	Underground Conduit
39	B22-02483	840 ORANGEDALE AVE	PM	Water Pipe - Underground
40	B22-02482	848 ORANGEDALE AVE	PM	Sewer Lateral
41	B22-02482	848 ORANGEDALE AVE	PM	Ground Plumbing
42	B22-02482	848 ORANGEDALE AVE	PM	Underground Conduit
43	B22-02482	848 ORANGEDALE AVE	PM	Water Pipe - Underground
44	B22-02481	1720 SUNNY HEIGHTS LN	PM	Sewer Lateral
45	B22-02481	1720 SUNNY HEIGHTS LN	PM	Ground Plumbing
46	B22-02481	1720 SUNNY HEIGHTS LN	PM	Underground Conduit
47	B22-02481	1720 SUNNY HEIGHTS LN	PM	Water Pipe - Underground

Inspections for John Thompson

	Permit #	Address	AM/PM	Inspection Type
1	B21-01509	110 TERRACINA BLVD	AM	Ground Plumbing

Inspections for Mark Farrell

	Permit #	Address	AM/PM	Inspection Type
1	B22-01781	225 E FERN AVE	AM	Framing
2	B22-01781	225 E FERN AVE	AM	Building - Final
3	B22-02157	141 E PALM LANE DR	AM	Framing
4	B22-02157	141 E PALM LANE DR	AM	Rough Electrical Wiring
5	B22-02157	141 E PALM LANE DR	AM	Rough Plumbing
6	B22-02157	141 E PALM LANE DR	AM	Plenums/Duct/Vent
7	B22-01417	1321 E PALM AVE	AM	Electric Conduit
8	B22-01417	1321 E PALM AVE	AM	Plenums/Duct/Vent
9	B22-01417	1321 E PALM AVE	AM	Building - Final
10	B22-01417	1321 E PALM AVE	AM	Electric Wire
11	B21-01509	110 TERRACINA BLVD	AM	Forms and Footings

February 6, 2023 Inspections

12	B21-01509	110 TERRACINA BLVD	AM	Rough Plumbing
13	B22-03078	1200 E COLTON AVE	AM	Roof Deck
14	B23-00246	25 RYAN ST	AM	Electric Conduit
15	B23-00246	25 RYAN ST	AM	Electric Service
16	B23-00246	25 RYAN ST	AM	Building - Final
17	B23-00246	25 RYAN ST	AM	Electric Wire
18	B22-02230	30746 E SUNSET DR S	PM	Framing
19	B21-01601	644 E MARIPOSA DR UNIT 2	PM	Insulation
20	B20-01542	1375 FOUNTAIN PL	PM	Lathing
21	B20-01542	1375 FOUNTAIN PL	PM	Drywall
22	B23-00081	718 CHESTNUT AVE	PM	Electric Conduit
23	B23-00081	718 CHESTNUT AVE	PM	Building - Final
24	B23-00081	718 CHESTNUT AVE	PM	Electric Wire
25	B23-00081	718 CHESTNUT AVE	PM	Electric Service

Inspections for Robert Munoz

	Permit #	Address	AM/PM	Inspection Type
1	B22-00717	20 N SAN GORGONIO DR	AM	Roof Deck
2	B22-00717	20 N SAN GORGONIO DR	AM	Exterior Shear
3	B22-00717	20 N SAN GORGONIO DR	AM	Rough Plumbing
4	B22-01370	1226 W CYPRESS AVE	AM	Forms and Footings
5	B23-00226	523 S BUENA VISTA ST	AM	Electric Conduit
6	B23-00226	523 S BUENA VISTA ST	AM	Building - Final
7	B23-00226	523 S BUENA VISTA ST	AM	Electric Wire
8	B23-00226	523 S BUENA VISTA ST	AM	Electric Underground Conduit
9	B22-02670	631 ALVARADO ST	AM	Building - Final
10	B22-02516	602 GARFIELD WAY	AM	Lathing
11	B22-00137	918 BANYON DR UNIT 2	AM	Framing
12	B22-00137	918 BANYON DR UNIT 2	AM	Rough Electrical Wiring
13	B22-00137	918 BANYON DR UNIT 2	AM	Rough Plumbing
14	B22-00137	918 BANYON DR UNIT 2	AM	Plenums/Duct/Vent
15	B22-02746	1636 BENITA MARIE CREST	AM	Electric Conduit
16	B22-02746	1636 BENITA MARIE CREST	AM	Building - Final
17	B22-02746	1636 BENITA MARIE CREST	AM	Electric Wire
18	B22-02942	330 W MARIPOSA DR	AM	Drywall
19	B22-02606	1509 PAMELA CR	AM	Building - Final
20	B22-02717	30777 E SUNSET DR S	AM	Forms and Footings
21	B21-02108	1432 E HIGHLAND AVE	PM	Forms and Footings
22	B22-02362	911 E SHARON RD	PM	Framing
23	B22-02362	911 E SHARON RD	PM	Rough Electrical Wiring
24	B22-02362	911 E SHARON RD	PM	Rough Plumbing
25	B22-02362	911 E SHARON RD	PM	Gas Test
26	B22-01252	1002 TRIBUNE ST	PM	Exterior Shear
27	B23-00025	1116 COLUMBIA ST	PM	Electric Service
28	B23-00025	1116 COLUMBIA ST	PM	Building - Final
29	B23-00025	1116 COLUMBIA ST	PM	Electric Wire