

## November 9, 2018 Inspections

**Inspections for Andy McCune**

Permit Number	Address	Inspection Type
B16-15086	117 NORWOOD ST	Rough Electrical Wiring
B16-15086	117 NORWOOD ST	Framing
B16-15086	117 NORWOOD ST	Rough Plumbing
B18-01515	350 ALABAMA ST	Building - Final
B18-02264	526 ALVARADO ST	Rough Plumbing
B18-02053	819 MATTHEW CT	Roof Deck
B18-02264	526 ALVARADO ST	Building - Final
B18-02173	210 ORCHID CT	Building - Final
B18-01830	308 E PIONEER AVE	Plenums/Duct/Vent
B18-01985	861 KIMBERLY AVE	Plenums/Duct/Vent
B18-02222	1681 LIV CT	Forms and Footings
B18-02191	1418 E COLTON AVE	Building - Final
B18-01632	1582 FRANKLIN AVE	Ground Plumbing
B18-02063	909 FRONTIER AVE	Building - Final
B18-02250	417 JORDAN DR	Building - Final
B18-01632	1582 FRANKLIN AVE	Forms and Footings
B18-00144	1592 ADELINE AVE	Insulation
B18-01402	1017 DRACENA CT	Building - Final
B18-01985	861 KIMBERLY AVE	Building - Final
B18-01830	308 E PIONEER AVE	Building - Final
B18-02168	20126 TRACT	Building - Final
B18-02218	1680 LIV CT	Rough Plumbing
B18-02019	1529 ADELINE AVE	Sewer Lateral
B18-02020	1525 ADELINE AVE	Sewer Lateral
B18-02018	1521 ADELINE AVE	Sewer Lateral
B18-02021	1517 ADELINE AVE	Sewer Lateral

**Inspections for Randy Cowles**

Permit Number	Address	Inspection Type
B17-00401	207 BELMONT CT	Insulation